



Auper Electronic Controls Inc

How to enter a TM600 programming mode without an i-button key manager key.

1. Unplug the TM600
2. press and Hold the S/R button as you plug the power on. Release the S/R button.
3. You are asked to enter a sequence.

Press the buttons in following order:

▲ S/R, S/R, ▼, ▲, M

4. You are asked to Enter function number.
5. Press M to enter the programming modes.
6. Press up to reset the calibration values. Press Down to move to the next line.
7. press S/R to reset the report number.

Programming New Manager or User keys.

1. Enter the programming modes (Step 5 above).
2. Press the M button until you see "Manager Key" or "User key" (User keys can be used to clear the daily counters only)
3. Press ▲, ▼ to choose the key number you wish to use or add.
4. Apply the ibutton onto the probe. The new number will appear on screen.
5. Press S/R to accept.
6. To exit, apply the ibutton key to the probe.
7. To exit without ibutton key, unplug the TM600.